

Table6. Ranking of key factors affecting taxiing time at MUC airport

MAE/RMSE	Acc60	Acc180	Acc300
OperationType	OperationType	OperationType	OperationType
TaxiDistance	TaxiDistance	TaxiDistance	TaxiDistance
EuclideanDistance	EuclideanDistance	EuclideanDistance	EuclideanDistance
TurnCount	TurnCount	TurnCount	TurnCount
FlightCode	FlightCode	FlightCode	FlightCode
RunwayConfig	RunwayConfig	RunwayConfig	RunwayConfig
	AircraftModel	AircraftModel	AircraftModel
	RelativeHumidity_2m	RelativeHumidity_2m	RelativeHumidity_2m
	WindDirection	WindDirection	WindDirection
	FlightsWithin15Min		FlightsWithin15Min