

Supplementary Fig. S4 Soluble As concentrations in the overlying water (a) and porewater (b), the release fluxes of soluble As (c), as well as the correlation analysis between DO or Eh and the release flux of soluble As (d). Error bars represent standard deviations (\pm SD).