Slope/Rock Scaling	Date of Report	Site Location	Description of Damage	Emergency Repair	Permanent Repair
Damage				Estimated Costs	Estimated Costs
Pearl Hill/Cold Springs Fire	Information not	WA State Route 2 MP	There are areas in drainages and sensitive slopes that	\$0.00	\$26,940.45
DDIR Site Number	provided	167.20 - 172.26	will need to be		
DMB075 - 01			hydroseeded with seed, fertilizer & mulch to help		
			stabilization the slope to prevent erosion.		

Supplemental Table S9 – Costs of Slope/rock Scaling Damage from the 2020 Washington Labor Day Wildfires.